
Pulse Train Input Type, Servo System, DC Type

Features



- No tuning necessary, easy operation
- Fast response rate, no hunting and retain torque when stopped
- Various resolutions (electrical gears) and integrated alarm function
- Higher cost-efficiency compared to conventional servo motors
- Available in motor frame size 42mm, 56mm





NEW

[AiS-42 Series]

[AiS-56 Series]




Please read "Caution for your safety" in operation manual before using.



Applications

• Semiconductor equipment, 3D printer, Optical inspection equipment, chip mounter, cartesian robot, conveying equipment, alignment stage, etc.

Ordering Information



Model

Set	Driver	Motor
AiS-42SA	AiS-D-42SA	Ai-M-42SA
AiS-42MA	AiS-D-42MA	Ai-M-42MA
AiS-42LA	AiS-D-42LA	Ai-M-42LA
AiS-56SA	AiS-D-56SA	Ai-M-56SA
AiS-56MA	AiS-D-56MA	Ai-M-56MA
AiS-56LA	AiS-D-56LA	Ai-M-56LA

Specifications

O Driver

Model		AiS-D-42SA	AiS-D-42MA	AiS-D-42LA	AiS-D-56SA	AiS-D-56MA	AiS-D-56LA
Power su	upply	24VDC					
Allowable	e voltage range	90 to 110% of the rated voltage					
Current	STOP*1	Max. 6W	Max. 6.5W	Max. 7W	Max. 8W	Max. 9W	Max. 10W
consump	otion Max. during operation*2	Max. 60W	Max. 60W Max. 120W				
Max. RU	IN current ^{**3}	1.7A/Phase			3.5A/Phase		
STOP cu	ırrent	25% or 50% of n	nax. RUN current	(set by SW3 swit	ch)		
Resolutio	on	500, 1000, 1600	2000, 3200, 360	0, 5000, 6400, 72	200, 10000P/R		
Pulse inp	out method	1 pulse or 2 puls	e input method (s	et by SW3 switch	1)		
Status in	dicator	Power indicator:	green LED, Alarm	n indicator: red LE	D, In-position inc	dicator: Yellow LEI	D
nput sig	nal	RUN pulse, HOL	D OFF, Alarm res	et (photocoupler	input)		
Output s	ignal	In-position, Alarn	n output (photoco	upler output), End	coder signal (A, Ā	\overline{A} , B, \overline{B} , Z, \overline{Z} phase) (line driver output
e SL	Pulse width	CW, CCW: Input pulse frequency duty 50% (±5%), HOLD OFF: Min. 1ms, ALARM RESET: Min. 20ms					
ulse	Rising/Falling time	CW, CCW: Max. 0.5µs					
t i	Pulse input voltage	[H]: 4-8VDC, [L]: 0-0.5VDC					
Input pulse specifications	Max. input pulse freq. **4	CW, CCW: 500kHz					
nput res	istance	220Ω (CW, CCW), 270Ω (HOLD OFF, ALARM RESET)					
nsulatio	n voltage	Min. 100MΩ (at	500VDC megger)				
Dielectri	c strength	1,000VAC 60Hz	for 1min.				
Vibration	1	1.5mm amplitude	e at frequency of	10 to 55Hz (for 1	min.) in each X, \	Y, Z direction for 2	hours
Shock		300m/s ² (approx. 30G) in each X, Y, Z direction for 3 times					
Environ-	Ambient temperature	10 to 50°C, storage: -10 to 60°C					
ment	Ambient humidity	35 to 85%RH, storage: 35 to 85%RH					
Approva	I	(€ Rous					
Weight**	ight ^{×5} Approx. 400g (approx. 290g)						
×1: Base	ed on the ambient temp	erature 25°C, amb	ent humidity 55%	RH and STOP o	urrent 50%		,

- X1: Based on the ambient temperature 25°C, ambient humidity 55%RH, and STOP current 50%.
- **2: Max. power consumption during operation. When changing the load rapidly, instantaneous peak current may increase. The capacity of power supply should be over 1.5 to 2 times of max. power consumption.
- ※3: RUN current varies depending on the input RUN frequency and max. RUN current at the moment varies also.
- **4: Max. input pulse frequency is max. frequency to be input and does not same as max. pull-out frequency or max. slewing frequency.
- X5: The weight includes packaging. The weight in parentheses is for unit only.
- XEnvironment resistance is rated at no freezing or condensation.

Motor

_						
Model	Ai-M-42SA	Ai-M-42MA	Ai-M-42LA	Ai-M-56SA	Ai-M-56MA	Ai-M-56LA
Max. holding	2.81kgf·cm	4.65kgf·cm	5.1kgf·cm	7.65kgf·cm	12.6kgf·cm	23.5kgf·cm
torque ^{*1}	(0.275N·m)	(0.45N·m)	(0.5N·m)	(0.75N·m)	(1.23N·m)	(2.3N·m)
	38g·cm ² (38×10 ⁻⁷ kg·m ²)	55g·cm ² (55×10 ⁻⁷ kg·m ²)	80g·cm ² (80×10 ⁻⁷ kg·m ²)	120g·cm ² (120×10 ⁻⁷ kg·m ²)		520g·cm ² (520×10 ⁻⁷ kg·m ²)
Weight ^{**2}	Approx. 0.49kg (approx. 0.3kg)	Approx. 0.56kg	Approx. 0.63kg	Approx. 0.73kg	Approx. 0.92kg	Approx. 1.35kg (approx. 1.17kg)

Common specifications

• 0011111101	i specifications	
Basic step and	gle	1.8°/step
Number of ph	ases	2-phase
Operation me	thod	Bipolar
Max. allowable	e speed	3000rpm
Insulation class	SS	B type (130°C)
Insulation resi	istance	Min. 100MΩ (at 500VDC megger), between motor coil-case
Dielectric stre	ngth	500VAC 50/60Hz for 1 min., between motor coil-case
Environment	Ambient temperature	0 to 50°C, storage: -20 to 70°C
Environment	Ambient humidity	20 to 90%RH, storage: 15 to 95%RH
Radial movem	nent	Max. 0.025mm (load 5N)
Protection stru	ucture	IP30 (IEC standards)

- **1: Max. holding torque is standard torque when supply the rated current (2-phase holding) and stop the motor for comparing the specifications of motors.
- ※2: The weight includes packaging. The weight in parentheses is for unit only.
- ※Environment resistance is rated at no freezing of condensation.

(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encode

(I) SSRs / Power Controllers

(N) Display Units

(P) Switching Mode Power Supplies

AiS Series


Dimensions


(unit: mm)

Motor

* For flexible coupling (ERB Series) information, refer to F-64 page.

•Ai-M-42 Series







(unit: mm)

Model	L1
Ai-M-42SA	33
Ai-M-42MA	39
Ai-M-42LA	47.5

•Ai-M-56 Series







(unit: mm)


Model	L1
Ai-M-56SA	41
Ai-M-56MA	54.5
Ai-M-56LA	78.5

O Driver




150





Driver Unit Descriptions



Driver Status Indicators

Name	LED Color	Function	Descriptions
PWR	Green	Displays power input	Turns ON when the unit operates normally after supplying power
AL	Red	Displays alarm	Flashes for alarm status.
INP.	Yellow	Displays complete in-position	Turns ON when motor is placed at command position after positioning input.


Driver Setting


SW1: Motor drive response setting switch (speed filter)

XSet motor drive response for input pulse.

XSet the delay time between the position of input pulse and the position of motor to prevent load changing or disturbance with soft operation

XIf the setting value is too high, the synchronous response by command is decreased.





<Graph for input speed and motor response>

O SW2: Micro step setting switch (Resolution)

XSet the micro step resolution of driver.

**The number of pulses per 1 rotation by resolution is each 500, 1000, 1600, 2000, 3200, 3600, 5000, 6400, 7200, 10000.

Setti	ng switch	Setting	Pulse/1 Revolution	Resolution
		0 (Factory default)	500	2.5
		1	1000	5
	-	2	1600	8
	b 5 6 .	3	2000	10
m	(売):	4	3200	16
4	4 0 6	5	3600	18
	750	6	5000	25
	RES	7	6400	32
		8	7200	36
		9	10000	50

(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encode

(I) SSRs / Power Controllers

(J) Counters

(M) Tacho / Speed / Pulse Meters

(N) Display Units

(O) Sensor Controllers

(P) Switching Mode Powe Supplies

l = No	No.	No. Name		Switch position		
♦ ■ ■	INO.	INdille	Function	ON	OFF (Factory default)	
ON	1	CD	STOP current	25% of max. RUN current	50% of max. RUN current	
	2	1P/2P	Pulse input method	1-pulse input method	2-pulse input method	


STOP current

Pulse input method

CW: Rotation operation signal input

CCW: Rotation direction signal input


([H]: Forward rotation, [L]: Reverse rotation)



[H]: Photocoupler ON (voltage of both ends 4-8VDC)

CW: Forward rotation signal input

CCW: Reverse rotation signal input



[L]: Photocoupler OFF (voltage of both ends 0-0.5VDC)

Control Input/Output

Inner signal of all input/output consists of photocoupler.

ON, [H]: photocoupler power ON/ OFF, [L]: photocoupler power OFF.

⊚ Input

1. HOLD OFF

- •This signal is for rotating motor's axis using external force or used for manual positioning.
- •When hold off signal maintains over 1ms as [H], motor excitation is released.
- •When hold off signal maintains over 1ms as [L], motor excitation is in a normal status.
- *When supplying hold off signal, in-position output and LED turn OFF.
- XStop the motor for using this signal.
- *Refer to example of input circuit connection.


2. ALARM RESET

- •This signal is for clearing the alarm.
- •When alarm reset signal maintains over 20ms as [H], alarm is cleared. The alarm LED and alarm output turns OFF and the driver returns to normal status.
- XIf the alarm causes are not removed clearly and using alarm reset, driver may not be returned at the normal status.
- ※Refer to example of input circuit connection.


3. Example of input circuit connection

-When using 5VDC for VCC, short the R_L In case of over 5VDC (below 30VDC is recommended), use the R_L for I_F of photo coupler (forward current of primary LED) to be within 10mA following the below formula.

$$R_L = \frac{V_{CC} - 1.25V}{0.01A} - 270\Omega$$




C. Circuit with NPN (not-reversed)



VCC 270Ω

D. Circuit with PNP (reversed)

B. Pull-Down



Driver

Output

1. In-Position

In-position output is motor drive complete signal and it is output when drive is complete by command pulses.

- When motor is arrived at the command position, in-position output is [H]. (position error=0)
- When drive is complete and motor rotates by the external force,
- -1.8°≤ Position error ≤ 1.8°: In-position = [H]

Position error < -1.8°, Position error > 1.8°: In-position = [L]

The in-position LED turns ON/OFF depending on in-position output [H]/[L].

For accurate drive, check the in-position output again and execute the next drive.

*Refer to example of output circuit connection.

2. ALARM OUTPUT

When alarm occurs, driver recognizes the alarm. The alarm LED (red) and alarm output represents the errors.

- Alarm output signal
 - -In case of normal status, output is [H]. When alarm occurs, output is [L].
 - -When supplying alarm reset, output turns [H].


*Refer to example of output circuit connection.

Alarm indicator

Depending on the number of flashing of alarm indicator, you can check alarm causes.

No. of flashing	Alarm type	Descriptions
1	Over current error	When over current flows at motor RUN element
2	Over speed error	When motor speed is over 4,000rpm
3	Position tracking error	When motor does not track the pulse input normally
4	Over load error	When applying over the rated load for over 1 sec.
5	Over heat error	When driver inner temperature is over 80°C
6	Motor connection error	When supplying power without connecting motor cable to the driver
7	Encoder connection error	When encoder cable connection error occurs at driver

*Depending on alarm type, it flashes the number of flashing with 400ms interval. The waited 800ms signals output repeatedly. Until clearing alarm by alarm reset signal, alarm signal output continuously.



3. Example of output circuit connection


-It is recommended to use below 50VDC at VCC. Use the R_L for I_C (collector current of secondary detector) of photo coupler inside the driver to be within 25mA following the below formula.

$$\times A: R_L = \frac{V_{CC}-0.7V-V_F}{0.025A} - 10\Omega$$


$$\times B,C: R_L = \frac{V_{CC}-0.7V}{0.025A} - 10\Omega$$

(V_F is LED forward voltage of primary photocoupler.)


A. Circuit with photo coupler



B. Circuit with pull up (reversed)



C. Circuit with pull down (not-reversed)



(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encode

(I) SSRs / Power Controllers

(J) Counters


(N) Display Units


(O) Sensor Controllers

(P) Switching Mode Powe Supplies

4. Encoder output (line driver output)

•Encoder output phase





Connection Connectors of Driver

© Connector function

• Power connector (CN1)

Pin arrangement	Pin no.	Function
	2	GND
1	1	24VDC

Motor+Encoder Connector (CN2)

Pin arrangement	Pin no.	Function	Pin no.	Function
	1	GND	8	+5VDC
14 13 9 8	2	ENCODER A	9	ENCODER Ā
	3	ENCODER B	10	ENCODER B
	4	ENCODER Z	11	ENCODER Z
	5	GND EARTH	12	N·C
7 6 2 1	6	MOTOR A	13	MOTOR B
	7	MOTOR Ā	14	MOTOR B

• I/O connector (CN3)

Pin arrangement	Pin no.	Input/ Output	Function	Pin no.	Input/ Output	Function
	1	Input	CW+	11	Output	END+
	2	Input	CW-	12	Output	END-
	3	Input	CCW+	13	_	N·C
10 1	4	Input	CCW-	14	_	N·C
	5	Input	HOLD OFF+	15	Output	ENCODER A
	6	Input	HOLD OFF-	16	Output	ENCODER A
20 11	7	Output	ALARM OUT+	17	Output	ENCODER B
	8	Output	ALARM OUT-	18	Output	ENCODER B
	9	Input	ALARM RESET+	19	Output	ENCODER Z
	10	Input	ALARM RESET-	20	Output	ENCODER Z

© Connector specifications

Type		Specifications	Specifications				
		Connector Connector terminal		Housing	Manufacture		
ICN1		LAD1140-02(X)	_	_			
		CHD1140-02	CTD1140		HANLIM		
CN2	Driver	35318-1420	_		Molex		
CINZ	Motor+Encoder	5557-14R	5556T	_	Iviolex		
CN3	Driver	10220-52A2 PL		_	3M		
CINS	I/O connector	10120-3000PE		10320-52F0-008	SIVI		

*Above connectors are suitable for AiS Series. You can use equivalent or substitute connectors.

© Cable (sold separately)

Туре		Model	Model					
		CJ-MP20-HP⊡ (sold separately) ^{×1}						
		1 2 3 4 5 6 7 8 9 10						
		Pin No.	Cable color	Dot line color-numbers	Pin No.	Cable color	Dot line color-numbers	
		1		Black-1	11		Black-1	
I/O cable		2		Red-1	12	7	Red-1	
		3		Black-2	13	7	Black-2	
		4		Red-2	14		Red-2	
		5	Yellow	Black-3	15	White	Black-3	
		6	Yellow	Red-3	16	vvriite	Red-3	
		7		Black-4	17		Black-4	
		8		Red-4	18		Red-4	
				Black-5	19]	Black-5	
		10	7	Red-5	20	1	Red-5	
Motor+Encod	der cable							
	Normal	C1D14M-	*2	·				
	Moving	C1DF14M			-			
∢1· □ indicat				100) E.g.) CJ-MP20-HP070): 7m I/O ca	hle		

X2: ☐ indicates cable length (1, 2, 3, 5, 7, 10) E.g.) C1DF14M-10: 10m moving type motor+encoder cable

(A) Photoelectric Sensors

(C) Door/Area Sensors


(D) Proximity Sensors

(E) Pressure Sensors

(I) SSRs / Power Controllers

(P) Switching Mode Power Supplies

Connection For Motor And Driver




 $\mbox{\em XTo}$ input signal over 12VDC, connect external resistance for photocoupler I_F to be within 10mA.

两相步进电机马达样本闭环步进电机驱动器说明书 韩国Autonics步进伺服马达选型样本pdf资料 Closed-Loop Stepper Motor System

■ Motor Characteristics

● Ai-M-42SA



Ai-M-42MA

Ai-M-56SA

Torque(kgf·cm)


20

15

10

5

0 L 10



(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(G) Connectors/ Sockets

(I) SSRs / Power Controllers

(M) Tacho / Speed / Pulse Meters

(N) Display Units

(P) Switching Mode Power Supplies

● Ai-M-56MA

Ai-M-42LA

6


4

3

2

0 10

Torque(kgf·cm) 5




100

500

1000

Rotation speed(rpm)

● Ai-M-56LA



100

500

1000

Rotation speed(rpm)


(R) Graphic/ Logic Panels


(S) Field Network Devices

Motor Installation

1. Mounting direction

Motor can be mounted in any directions-facing up, facing down and side ways. No matter which direction motors to be mounted, be sure not to apply overhung or thrust load on the shaft. Refer to the table below for allowable shaft overhung load / thrust load.





X1: The distance from the shaft in front (mm)

Motor size	Permissible overhung	Allowable thrust load				
	D=0	D=5	D=10	D=15	Allowable tillust load	
Ai-M-42 Series	2 (20)	2.5 (25)	3.5 (34)	5.3 (52)	I lader the lead of motor	
Ai-M-56 Series	5.6 (55)	6.8 (67)	9.1 (89)	13.3 (130)	Under the load of motor	

Do not apply excessive force on motor cable when mounting motors.


Do not forcibly pull or insert the cable. It may cause poor connection or disconnection of the cable. In case of frequent cable movement required application, proper safety countermeasures must be ensured.




(unit: mm)


2. Mounting method


•Ai-M-42 Series







•Ai-M-56 Series










With considering heat radiation and vibration isolation, mount the motor as tight as possible against a metal panel having high thermal conductivity such as iron or aluminum.

When mounting motors, use hexagon socket screws, hexagon nuts, spring washers and flat washers. Refer to the table below for allowable thickness of mounting plate and using bolt.

两相步进电机马达样本闭环步进电机驱动器说明书 韩国Autonics步进伺服马达选型样本pdf资料 Closed-Loop Stepper Motor System

3. Connection with load

When connecting the load, be sure of the center, tension of the belt, and parallel of the pulley. When connecting the load such as a pulley, a belt, be sure of the allowable thrust load, radial load, and shock. Tighten the screw for a coupling or a pulley not to be unscrewed. When connecting a coupling or a pulley on the motor shaft, be sure of damage of the motor shaft and the motor shaft bearing. Do not disassemble or modify the motor shaft to connect with the load.



4. Installation condition

Install the motor in a place that meets certain conditions specified below.

It may cause product damage if instructions are not following.

- The inner housing installed indoor (This unit is manufactured for attaching to equipment. Install a ventilation device.)
- @Within 0 to 50°C (at non-freezing status) of ambient temperature
- ③Within 20 to 90%RH (at non-dew status) of ambient humidity
- The place without explosive, flammable and corrosive gas
- The place without direct ray of light
- ®The place where dust or metal scrap is not entered into the unit
- The place where water, oil, or other liquid are not touched
- ®The place where strong alkali or acidity does not exist closely
- The place where easy heat dissipation could be made
- @The place where no continuous vibration or severe shock
- The place with less salt content
- @The place with less electronic noise occurs by welding machine, motor, etc.
- ®The place where no radioactive substances and magnetic fields exist. It shall be no vacuum status as well.

Applications



(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encoders

(I) SSRs / Power Controllers

(J) Counters


(M) Tacho / Speed / Pulse Meters

(N) Display Units

(O) Sensor Controllers

(P) Switching Mode Powe Supplies

System Configurations



■ AiS-D Series, AFS-H20, and CJ cable Connection

CJ-MP20-HP Series		AiS-D Series		AFS-H20 and CJ-HPMP20-H1N□-1ANR connection	AFS-H20 and CJ-HPMP20-H1N□-3ANR connection	
Pin No.		Dot color-No. of Dot(s)	Driver function		Terminal No.	Terminal No.
1	Yellow	Black-1	Input	CW+	A1	B1
2	Yellow	Red-1	Input	CW-	B1	A1
3	Yellow	Black-2	Input	CCW+	A2	B2
4	Yellow	Red-2	Input	CCW-	B2	A2
5	Yellow	Black-3	Input	HOLD OFF+	A3	B3
6	Yellow	Red-3	Input	HOLD OFF-	B3	A3
7	Yellow	Black-4	Output	ALARM+	A4	B4
8	Yellow	Red-4	Output	ALARM-	B4	A4
9	Yellow	Black-5	Input	ALARM RESET+	A5	B5
10	Yellow	Red-5	Input	ALARM RESET-	B5	A5
11	White	Black-1	Output	END+	A6	B6
12	White	Red-1	Output	END-	B6	A6
13	White	Black-2	_	N-C	A7	B7
14	White	Red-2	_	N·C	B7	A7
15	White	Black-3	Output	Encoder A	A8	B8
16	White	Red-3	Output	Encoder Ā	B8	A8
17	White	Black-4	Output	Encoder B	A9	В9
18	White	Red-4	Output	Encoder B	B9	A9
19	White	Black-5	Output	Encoder Z	A10	B10
20	White	Red-5	Output	Encoder Z	B10	A10

■ Ai-SERVO

1)System overview


Ai-Servo is a closed-loop stepper motor system that combines the strengths of stepper motor systems and servo motor systems.


The integrated encoder allows accurate motor movement through feedback, a characteristic of servo motors.

As with stepper motors, Ai-Servo has a fast response rate for continuous short stroke positioning and does not have hunting problem, reducing vibrations.

Ai-Servo does not need to be tuned during initial setup, is equipped with various alarm functions, and boasts higher torque and reduced overheating problems.

2)Control properties





When rotating the motor while stopped, the encoder detects the rotation of the motor and controls the motor so that it generates the maximum torque.

3) Feature comparision between Ai-SERVO and conventional system

		-	
	Stepper system	Ai-SERVO	Servo system
Accuracy	Low position control accuracy	High position control accuracy	High position control accuracy
Hunting	No hunting when stopped	No hunting when stopped	Hunting when stopped
Low speed operation	Vibration in low speed	Low vibrations in low speed	Low vibrations in low speed
Continuous drive	High response rate	High response rate	Slower response rate (correction time)
System setting	Quick and easy setting	Quick and easy setting	Gain tuning required
Applications	Optimized for short continuous high- speed drive	Optimized for lengthy high-speed drive	Optimized for lengthy high-speed drive

Features

1) Fast response rates and accurate position control

The integrated encoder compares the current position with the received command pulse then provides feedback, allowing for accurate positioning.

Controller Motor+Encoder Pulse signal Driver $\mathbf{U}\mathbf{U}\mathbf{U}$ Positioning com-Encoder signal pleted signal

2) 10-stage resolution


Alarm signal

10-stage resolution of up to 10,000 P/R allows highly precise position control (up to 0.036°).



3) No hunting for accurate stop positioning

Unlike servo systems which require hunting (fine vibration) when stopped, AiS series does not require hunting for stable and accurate stop positioning.



(A) Photoelectric Sensors

(C) Door/Area Sensors

(D) Proximity Sensors

(E) Pressure Sensors

(F) Rotary Encode

(I) SSRs / Power Controllers

(J) Counters

(M) Tacho / Speed / Pulse Meters

(N) Display Units

(O) Sensor Controllers

(P) Switching Mode Powe Supplies

两相步进电机马达样本闭环步进电机驱动器说明书 韩国Autonics步进伺服马达选型样本pdf资料 AIS Series

4) Motor temperature chart


Minimized heat generation by managing the current flowing through the motor with load.

*Result of Autonics test

(Drives 50 times and stops 1 min. repeatedly

at 29±1°C ambient temperature)

•L type of frame size 42mm motor



5) Tuning not required

Tuning is unnecessary even with load changes. (no gain tuning)



Proper usage

Troubleshooting

1. When motor does not rotate

- ①Check the connection status between controller and driver, and pulse input specifications (voltage, width).
- ②Check the pulse and direction signal is connected correctly.

2. When motor rotates to the opposite direction of the designated direction

- When RUN mode is 1-pulse method, CCW input [H] is for forward, [L] is for backward.
- When RUN mode is 2-pulse method, check CW and CCW pulse input is changed.

3. When motor drive is unstable

- ①Check that driver and motor is connected correctly.
- ②Check the driver pulse input specifications (voltage, width).

O Caution during use

Motor

1. Do not disassemble or modify the product.

It may cause malfunction due to small dregs. Once disassembling the motor, its performance would significantly decline.

2. Do not impact the motor.

The air-gap, the distance between rotator and stator is processed as 0.05mm, but if it is impacted, the balance of air-gap can be broken and it may cause a malfunction.

This encoder consists of precision components. Therefore, if it is dropped or has strong shock, it may lose the function or generates wrong output pulses.

3. Using at low temperature

Using motors at low temperature may cause reducing maximum starting / driving characteristics of the motor as ball bearing's grease consistency decreases due to low temperature. (Note that the lower the bearing's grease consistency, the higher the bearing's friction torques.) Start the motor in a steady manner since motor's torque is not to be influenced.

4. Temperature rise

The surface temperature of motor shall be under 100°C and it can be significantly increased by operation conditions. In this case, use the cooling fan to lower the temperature forcedly.

5. Insulation resistance measurement, Dielectric strength test When executing insulation resistance measurement or dielectric strength test when motor and driver are connected, it may cause damage to the unit.

6. Maintenance, Inspection

For using motor, it is recommended to Maintenance and inspection regularly.

If motor has error, do not use the motor. Take maintenance and inspection before using it.

Maintenance and inspection items are as below.

- Unwinding bolt and connection parts for the unit installation and load connection
- ②Strange sound from ball bearing of the unit
- ③Damage and Stress of lead cable of the unit
- 4 Connection error with driver
- ⑤ Inconsistency between the axis of motor output and the center, concentric (eccentric, declination) of the load, etc.

Driver

1. Caution for signal input

If the signal input supply is higher than rated supply in the specification, connect the additional resistance to external part. (Connect $3k\Omega$ of resistance when applying 24V of power)

2. Caution for wiring

(XAutonics product is recommended)

- Use twisted pair (over 0.2mm²) for the signal cable which should be shorter than 2m.
- ② The thickness of cable should be same or thicker than the motor cable's when extending the motor cable.
- ③ Must separate between the signal cable and the power cable over 10cm.

3. Caution for installation

For heat radiation when installing this unit, contact this driver base tightly with the metal surface. When using this unit, overheat error occur, install a fan for heat radiation or change the installation placement.

4. Caution for re-supplying power

Re-supply power after min. 1 sec. from disconnected power.

5. Motor vibration and noise can occur in specific frequency period

- Motor vibration and noise can be lowered by change motor installation or attach damper.
- ②Use the unit in a range without vibration and noise range by RUN speed adjustment.

6. This product may be used in the following environments

- ①It shall be used indoor
- ②Altitude up to 2,000m
- ③Pollution degree 2
- 4 Installation category II