



LEE INSTRUMENTS

L 360 涂层测厚仪用户快速使用指南

包装

L 360 主机

铁基底材

认证标准片组

随机电池和挂绳等

操作指南

1、预热

按操作键一次进入预热状态，屏幕出现 READY！即预热完毕进入工作状态。（建议每次使用前预热一次）

2、底材校正

按操作键两次进入底材校正状态，屏幕出现 BASE ZERO，将测量探头与待测底材表面垂直接触并轻轻压住，提示音响过后之后提起探头。

3、三点全量程校准

按操作键三次进入三点全量程校准状态，按照提示“USER CAL BASE→S1→S2→S3→DONE”进行校准。屏幕上出现“DONE”即完成校准，可进行测量。

4、单位转换

按操作键四次，um 和 mil 单位之间自动切换。

45 秒钟内无操作，电源自动关闭。

测量范围：100—6000um 或 100—240mil

测量精度： $\pm [(1\% \sim 3\%)H + 1\text{um}]$ 注： H 是厚度读数

联系地址： 2506 Abbott Rd. P07, Midland, MI, 48642, USA

联系电话： 001-515-520-0909



LEE INSTRUMENTS

L 360 Coating Thickness Gauge User Guide

Materials

L 360 Gauge	Reference Fe Base
Certified Plastic Shims	Battery etc.

Operation Guide

1、 Warm-up

Keystroke once; wait for 2 seconds before “READY!” is displayed on the LCD. (Recommended)

2、 Zeroing

Keystroke twice; when “BASE ZERO” is displayed, place flat on surface; hold steady. After measurement is obtained, new reading is shown and gauge beeps. Then lift gauge.

3、 User Calibration

Keystroke three times; follow instruction shown on the LCD “USER CAL BASE→S1→S2→S3→DONE”. When “DONE” is displayed, it is ready for use.

4、 Unit Change

Keystroke four times, convert from ums to mils or vice versa.

L 360 powers down after 45 seconds of no activity.

Measurement Range: 100—6000um or 100—240mil

Accuracy: $\pm [(1\% \sim 3\%)H + 1\text{um}]$ Note: H is thickness reading

Address: 2506 Abbott Rd. P07, Midland, MI, 48642, USA

Phone: 001-515-520-0909